

## FEATURES

- Arduino and Raspberry Pi client software libraries.
- Dust and waterproof
- Calibration functions for Dielectric permittivity(and Expermetal EC)
- Low cost and easy to use.
- Fairly accurate readings





## PM-WCS-3-I2C I2C Capacitive soil moisture, temperature sensor

## ELECTRICAL PROPERTIES

	Min/Sleep	Typical	Max
Supply voltage (VCC), V	2.2	3.3	5v
Working current (VCC=3.6V), mA	-	12	14
Operating Temperature Range, Celsius	-20	25	70

In case your application needs to power up sensor before measurement, time to wait before taking measurement is 100ms (1.7s for old version before v1.1).

### MEASUREMENT PROPERTIES

	Resolution	Range /avg Tolerance
Dielectric permittivity ( $\epsilon$ ) (Temperature corrected) Volumetric water content - VWC calculation from Dielectric permittivity $\epsilon$ . VWC = 0.002974 * pow( $\epsilon$ ,2) + 0.07424 * $\epsilon$ -1.295;	0.1ε	1 (air) to 80 (water) /5%
Expermetal EC, Electrical Conductivity (mS/m) (0.1 mS/m = 1 uS/cm)	0.1 mS/m	0300 mS/m 20% 300800 mS/m 40%
Temperature (°C)	0.1°C	-20 to 70°C/3%
Degree of water saturation in the soil	0.1%	0-100% /8%

#### PHYSICAL PROPERTIES

Sensor dimensions 114 x 24 x11 Cable length 1.5m



## **RASPBERRY PI** wiring to Raspberry Pi connector:

Raspberry Pi pin #1 - sensor **red** (3.3v) Raspberry Pi pin #3 - sensor **green** (SDA) Raspberry Pi pin #5 - sensor **white** (SCL) Raspberry Pi pin #9 - sensor **black** (GND) Raspberry Pi pin #9 - sensor shield(GND)

# Enable i2c interface in Raspberry Pi

see this manual

# Get software

This sample software demonstrates hot to make command line interface for the sensor. Sensor default I2C address is 0x63.

To get software execute following on Raspberry Pi:

git clone https://github.com/tinovi/i2cRaspberry

### cd i2cRaspberry

chmod 777 \*.sh to add permissions for execute

./mk.sh to make demo executable

./read.sh to read data from sensor

./svcs 0x63 addr 0x65 ( optional) to change default address 0x63 to new I2C address: 0x65

### CALIBRATION RASPBERRY

- 1) Download and install raspberry pi software described in previous section
- 2) cd i2cRaspberry cd to software directory
- 3) ./read.sh read data
- 4) **./cal\_air.sh** hold sensor in the air, and execute this command to calibrate sensor in the air
- 5) ./cal\_water.sh submerge sensor in the water or soil with the water, and execute this command to calibrate water.
- 6) ./cal\_ec.sh <ec uS/m> put sensor to the soil or calibration fluid with known uS/m and write correct uS/m
- 7) ./read.sh read data



## ARDUINO SDA and SCL lines require pullup resistors ~4.7k

## wiring to Arduiono:

Arduiono pin #3V3 - sensor **red** (3.3v) Arduiono pin #A4 - sensor **green** (SDA) Arduiono pin #A5 - sensor **white** (SCL) Arduiono pin #GND - sensor **black** (GND) Arduiono pin #GND - sensor shield (GND)

## **Get software**

This sample software demonstrates hot to read data from sensor. Sensor default I2C address is 0x63. Download Arduino library from <u>there.</u>