Align IC1 pin 1 mark

Solder in order:
IC1,C1,R1,R2 & R3.

C   R

Check LED polarity

Flip LED to solder reversed.

Solder the 4 LEDs on backside.

It's a bit tricky but add small
solder to ease soldering.

Flip the board

Check LED polatity & solder YELlOW LEDS

**USE this as Reference
Soldermask has not been updated**

Solder push button S1

Add small blob of solder to
pin pad and battery pad.

Place battery holder & solder
Place pin & solder