UCTRONICS

Assembly Instruction

SKU: U6166



www.uctronics.com

PACKING LIST

SD card Adapter×6


PoE HAT×6

Heat Sink for PoE HAT ×6


Power Swtich and Nut×6


Rack×1

Wire for Power Switch×6

Screw×12

M2.5 Nut×12

Hex Standoff×12

STEP

01



Fix the Pi and PoE HAT with nuts and hex standoffs

02



Insert into the rack

03



Fix your Pi and rack with screws

04



Insert SD card adapter

05



Insert the power switch

06



Stick the heat sink for PoE HAT

EXPLODED VIEW



CONNECT