Russian Slayer Exciter TESLA COIL





Building Manual



Disclaimer:

I, Mark Donners, The Electronics Engineer, may or may not endorse various Do-It-Yourself (DIY) projects and all DIY projects are purely "at your own risk". As with any DIY project, unfamiliarity with the tools and process can be dangerous. Posts should be construed as theoretical advice only.

If you are at all uncomfortable or inexperienced working on these projects (especially but not limited to electronics and mechanical), please reconsider doing the job yourself. It is very possible on any DIY project to damage belongings or void your property insurance, create a hazardous condition, or harm or even kill yourself or others.

I will not be held responsible for any injury due to the misuse or misunderstanding of any DIY project.

By using the information provided by me, (Website, Youtube, facebook and other social media), you agree to indemnify me, affiliates, subsidiaries and their related companies for any and all claims, damages, losses and causes of action arising out of your breach or alleged breach of this agreement (disclaimer).

The materials on this site are distributed "as is" and appear on the site without express or implied warranties of any kind, except those required by the relevant legislation. In particular I make no warranty as to the accuracy, quality, completeness or applicability of the information provided.

The information provided is for entertainment and promotional purposes only. You may not rely on any information and opinions expressed in it for any other purpose.

Disclaimer short version:

This is a DIY project, use any provided information and/or materials at your own risk! I am not responsible for what you do with it!



Make sure that you know what you are doing! High voltage can kill!

www.TheElectronicEngineer.nl

Get your PCB here: https://www.tindie.com/products/25729/

This are the parts you need to assemble the PCB:



							Supplier
Designator	Name	Footprint	Quantity	Manufacturer Part	Manufacturer	Supplier	Part
C2,C3	1u	CAP-TH_L17.5-W7.5-P15.00-D1.2	2	C352S105K64C322	faratronic	LCSC	C497219
D1	VS-HFA08TB60-M3	TO-220AC-2_L10.0-W4.5-P5.10-L	1	VS-HFA08TB60-M3	Vishay Intertech	LCSC	C468157
F1	Fuse-5x20mm	FUSE-HOLDER-5X20MM	1				
HS2,HS3	SK104 HEAT SINK bez	SK104-PAD	2	Optional			
U1	BT152-800	TO-220-3_L10.0-W4.5-P2.54-L	1	BT152-800	SEMIWARE	LCSC	C696677
C1	22uF	CAP-TH_BD16.0-P7.50-D1.2-FD	1	22uF 450V 16*20	ValuePro	LCSC	C10737
Q1	IRFP460PBF	TO-247AC-3_L15.8-W5.0-P5.46-L	1	IRFP460PBF	VISHAY	LCSC	C2595
D2,D3,D4	1N5408G	DO-201_BD5.3-L9.5-P13.50-D1.4-RD	3	1N5408G	ON	LCSC	C133247
D5	1.5KE440A	DO-201_BD5.3-L9.5-P13.50-D1.4-FD	1	1.5KE440A	RUILON	LCSC	C32473
D6	1.5KE15A	DO-201AD_BD5.3-L8.4-P12.50-D1.4-FD	1	1.5KE15A	CREATEK	LCSC	C434999
HS1	Fischer_SK409	HEATSINK_FISCHER_SK409_SOLDERPINS	1	Fischer_SK409			
R3,R4,R5	10ΚΩ	RES-TH_BD4.5-L11.5-P15.00-D0.6	3	MOF2WS-10KΩ±5%T	华星机电	LCSC	C714419
R6	1.5K	RES-TH_BD5.5-L15.0-P19.00-D0.8	1	MFR3WSJT-73-1K5	YAGEO	LCSC	C176600
R1,R2	10	RES-TH_BD11.0-L49.5-P56.00-D1.0	2	CR-L15W10ΩJ	Chian Chia Elec	LCSC	C216391
P6,P7,P1,							
P4,P5,P2	MKDSN1.5/2-5.08	CONN-TH_2P-P5.08_1714984	6	MKDSN1.5/2-5.08	Phoenix Contact	LCSC	C91153
P3	MKDSN1.5/3-5.08	CONN-TH_3P-P5.08_1729131	1	MKDSN1.5/3-5.08	Phoenix Contact	LCSC	C91154

You'll also need 4 chokes (used in Tl-lights as ballast) I used Philips BTA36L31 but others will also work 3 toggle switches to operate and a Potentiometer of 22K with a plastic dial (not metal: safety first!)

And you need to assemble a primary and secondary coil


 $\underline{www.The Electronic Engineer.nl}$

Document version: 1.1



Secondairy coil


Isolated copper wire AWG 32 (0.2 mm2)
1000 windings This is approx..25m total length
PVC Pipe 90mm diameter Length 30cm
Isolation varnish - Make sure to apply a thick layer of varnish to increase electric isolation





Thick isolated wire AWG 14 (approx. 2 mm2) 4 windings PVC Pipe 120mm diameter Length 30cm. This is the easy part. Just wind the wire around the pipe. Each winding 2cm apart from the other winding.






Chokes

You must make 2 sets of chokes. Each set had two chokes connected in parallel





www.TheElectronicEngineer.nl

Document version: 1.1



