



USART0		USART0	
ALT 1		ALT 2	
P0_2	RX	P1_2	CT
P0_3	TX	P1_3	RT
P0_4	CT	P1_4	RX
P0_5	RT	P1_5	TX
USART1		USART1	
ALT 1		ALT 2	
P0_2	CT	P1_4	CT
P0_3	RT	P1_5	RT
P0_4	TX	P1_6	TX
P0_5	RX	P1_7	RX

2x5 - 50MIL CC DEBUGGER CONNECTION

