

RAD-04 BOM

Parts List

C1, C2	2	10uf 25v
FB1, FB2	2	Ferrite Bead
J1	1	4 way MTA-156 type connector
J2, J3, J4, J5, J6, J7, J8	7	PJ301BM 3.5mm Jacks
U1	1	ElectroSmith 3340 submodule
P1, P2, P3, P4	4	10KB Alpha vertical 9mm pot
	2	10 Pin SIL Header socket
	4	Davies 1900H style knobs